# ROCK Pi 4 - Getting started

Requirements

For the following tutorial you are going to need some essential materials.

- ROCK Pi board

  - ROCK (Pi) 4 v1.5

- Power supply
  - The ROCK Pi 4 is powered by Type-C port and has a wide range of input voltage, from 6V to 12. This is

    the power supply adapter that I used.

- USB keyboard and mouse
  - With four USB-A connectors, ROCK (Pi) 4 can be equipped with a full sized keyboard and mouse.
- USB Keyboard

- A keyboard is used to access the terminal.

- USB Mouse
  - A USB mouse is necessary in the graphical installation of Debian.

- Monitor and display cable
  - ROCK (Pi) 4A, 4B, 4A Plus, 4B Plus, 4 SE is equipped with a full sized HDMI connector. HDMI capable

    monitor is recommended.

- microSD card with the correct ROCK Pi 4 image

  - a microSD card, larger than 8GB, class 10 or better

-

-